



[4910-13-P]

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. FAA-2012-0265; Directorate Identifier 2010-NM-216-AD; Amendment 39-17098; AD 2012-12-18]**

**RIN 2120-AA64**

**Airworthiness Directives; Dassault Aviation Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are superseding an existing airworthiness directive (AD) for certain Dassault Aviation Model FALCON 7X airplanes. That AD currently requires revising the Abnormal Procedures and Limitations sections of the Dassault F7X Airplane Flight Manual. This new AD requires a test of the power distribution control units (PDCU) cards and generator control units (GCU) cards to detect faulty components, and if any faulty components are found, replacing any affected PDCU or GCU card. This AD was prompted by a determination that additional actions are necessary to address the identified unsafe condition. We are issuing this AD to detect and correct a leakage failure mode of transient voltage suppression (TVS) diodes used on PDCU cards or GCU cards in the primary power distribution boxes (PPDB), which, in combination with other system failures, could lead to loss of controllability of the airplane.

DATES: This AD becomes effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may examine the AD docket on the Internet at

<http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the Federal Register on March 15, 2012 (77 FR 15293), and proposed to supersede AD AD 2010-18-03, Amendment 39-16416 (75 FR 51931, August 24, 2010).

On August 11, 2010, we issued AD 2010-18-03, Amendment 39-16416 (75 FR 51931, August 24, 2010). That AD required actions intended to address an unsafe condition on certain Dassault Aviation Model FALCON 7X airplanes. The preamble of

AD 2010-18-03 explains that we consider the requirements of that AD “interim action” and are considering further rulemaking to mandate inspection (testing) of the PDCU and GCU cards and replacement of faulty cards, as required by European Aviation Safety Agency AD 2010-0073, dated April 15, 2010. The planned compliance time for those actions would allow enough time for prior public comment on the merits of those actions. This proposed AD follows from that determination.

The unsafe condition is a leakage failure mode of TVS diodes used on PDCU or GCU cards in the PPDB, which, in combination with other system failures, could lead to loss of controllability of the airplane. You may obtain further information by examining the MCAI in the AD docket.

#### **Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (77 FR 15293, March 15, 2012) or on the determination of the cost to the public.

#### **Conclusion**

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

#### **Costs of Compliance**

We estimate that this AD will affect about 9 products of U.S. registry.

The actions that are required by AD 2010-18-03, Amendment 39-16416 (75 FR 51931, August 24, 2010), and retained in this AD take about 4 work-hours per product, at an average labor rate of \$85 per work hour. Based on these figures, the estimated cost of

the currently required actions is \$340 per product.

We estimate that it would take about 4 work-hours per product to comply with the new basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$3,060, or \$340 per product.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD. We have no way of determining the number of products that may need these actions.

#### **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### **Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

### **Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM (75 FR 51931, August 24, 2010), the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### **PART 39 - AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. The FAA amends § 39.13 by removing airworthiness AD 2010-18-03, Amendment 39-16416 (75 FR 51931, August 24, 2010), and adding the following new AD:

**2012-12-18 Dassault Aviation:** Amendment 39-17098. Docket No. FAA-2012-0265; Directorate Identifier 2010-NM-216-AD.

#### **(a) Effective Date**

This airworthiness directive (AD) becomes effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

#### **(b) Affected ADs**

This AD supersedes AD 2010-18-03, Amendment 39-16416 (75 FR 51931, August 24, 2010).

#### **(c) Applicability**

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated

in any category, all serial numbers except those on which Dassault Aviation Modification M724 is embodied.

**(d) Subject**

Air Transport Association (ATA) of America Code 24: Electrical Power.

**(e) Reason**

This AD was prompted by a determination that additional actions are necessary to address the identified unsafe condition. We are issuing this AD to detect and correct a leakage failure mode of transient voltage suppression (TVS) diodes used on power distribution control units (PDCU) cards or generator control units (GCU) cards in the primary power distribution boxes, which, in combination with other system failures, could lead to loss of controllability of the airplane.

**(f) Compliance**

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**(g) Retained Airplane Flight Manual (AFM) Revision**

This AFM revision is retained from AD 2010-18-03, Amendment 39-16416 (75 FR 51931, August 24, 2010): Within 30 days after September 8, 2010 (the effective date of AD 2010-18-03, revise the Abnormal Procedures and Limitations sections of the Dassault F7X AFM to include the following statement. This may be done by inserting copies of this AD into the AFM Limitations section and Abnormal Procedures section.

Upon display of ELEC:BUS MISCONFIG TIED in Crew Alerting System (Abnormal procedure 3-190-20), land at

nearest suitable airport

Upon display of ELEC:LH ESS PWR LO or ELEC:LH ESS NO PWR (Abnormal procedure 3-190-40), land at nearest suitable airport

Upon display of ELEC:RH ESS PWR LO and ELEC:RH ESS NO PWR (Abnormal procedure 3-190-45), land at nearest suitable airport

Upon display of HYD:BACKUP PUMP HI TEMP (Abnormal procedure 3-250-15), set off the pump and if the backup pump is still rotating (green) in hydraulic synoptic, descend to a safe altitude or below 15,000 ft

Caution: These temporary amendments take precedence over the same procedures displayed through the Electronic Check List (ECL) in the aeroplane.

Note 1 to paragraph (g) of this AD: When a statement identical to that in paragraph (g) of this AD has been included in the Limitations section and Abnormal Procedures section in the general revisions of the AFM, the general revisions may be inserted into the AFM, and the copy of this AD may be removed.

**(h) New Requirements of this AD: Test the PDCU and GCU Cards**

For airplanes identified in Dassault Mandatory Service Bulletin 7X-133, dated December 4, 2009: Within 9 months after the effective date of this AD, perform a test of the PDCU and GCU cards to detect faulty components, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin 7X-133, dated December 4, 2009. If any faulty components are found, before further flight, replace any affected PDCU or GCU card, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin 7X-133, dated December 4, 2009.

**(i) Optional Method of Compliance**



For airplanes identified in Dassault Mandatory Service Bulletin 7X-133, dated December 4, 2009: Accomplishing the actions specified in paragraph (h) of this AD, within 9 months after the effective date of this AD, in accordance with the service information specified in paragraphs (i)(1), (i)(2), and (i)(3) of this AD, is acceptable for compliance with the actions specified in paragraph (h) of this AD.

(1) Goodrich Service Bulletin 80232190-24-01, dated August 13, 2009.

(2) Goodrich Service Bulletin 80232191-24-01, dated August 13, 2009.

(3) Goodrich Service Bulletin 80232192-24-01, dated August 13, 2009.

**(j) Other FAA AD Provisions**

The following provisions also apply to this AD:

**(1) Alternative Methods of Compliance (AMOCs):** The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be e-mailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

**(2) Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

**(k) Related Information**

Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2010-0073, dated April 15, 2010, and the service bulletins specified in paragraphs (k)(1) through (k)(4) of this AD, for related information.

(1) Dassault Mandatory Service Bulletin 7X-133, dated December 4, 2009.

(2) Goodrich Service Bulletin 80232190-24-01, dated August 13, 2009.

(3) Goodrich Service Bulletin 80232191-24-01, dated August 13, 2009.

(4) Goodrich Service Bulletin 80232192-24-01, dated August 13, 2009.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise.

(i) Dassault Mandatory Service Bulletin 7X-133, dated December 4, 2009.

(3) If you accomplish the optional actions specified by this AD, you must use the following service information to perform those actions, unless the AD specifies otherwise.

(i) Goodrich Service Bulletin 80232190-24-01, dated August 13, 2009.

(ii) Goodrich Service Bulletin 80232191-24-01, dated August 13, 2009.

(iii) Goodrich Service Bulletin 80232192-24-01, dated August 13, 2009.

(4) For Dassault service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>. For Goodrich service information identified in this AD, contact Goodrich Corporation, Power Systems, 1555 Corporate Woods Parkway, Uniontown, Ohio 44685-8799; telephone 330-487-2007; fax 330-487-1902; e-mail [twinsburg.techpubs@goodrich.com](mailto:twinsburg.techpubs@goodrich.com); Internet <http://www.goodrich.com/TechPubs>.

(5) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html)

Issued in Renton, Washington, on June 11, 2012.

Kalene C. Yanamura,  
Acting Manager,  
Transport Airplane Directorate,  
Aircraft Certification Service.

[FR Doc. 2012-15066 Filed 06/22/2012 at 8:45 am; Publication Date: 06/25/2012]